HUMAN ACTIVE TECHNOLOGY™

7000
Installation Instructions



Human Active Technology
800 524 2744
customerservice@team-hat.com
team-hat.com

© 2024 Human Active Technology, LLC P516213 REV C

PARTS LIST

A Top Down Mount 1x
8524



B Monitor Tilter 1x
405397



C 75/100mm VESA Adapter Plate 1x
105587



D 10-32 x 3/8" Phillips Flat Head Screw (4-pack) 1x
702281

E M4 x 12mm Phillips Pan Head Screw (4-pack) 1x
702096



F Dog Washer 1x
105189



G 10-32 x 3/8" FPhMS w/Lock Patch 1x
705198

H Cable Cap 1x
114810



I 1/8" Allen Wrench 1x
701312

J 3/32" Allen Wrench 1x
700146

K 7/32" Allen Wrench 1x
701127



L 6mm Allen Wrench 1x
717654



M Forearm Cable Cap 1x
115584



N* M8 x 95mm SCHS 1x
716061



O* Spacer 1x
701544



P* Lock Nut 1x
710015

* Included with optional thru-desk kit only, 8524-TM-CK (sold separately).

DESK CLAMP CONFIGURATION

1



Desk thickness
up to 1.5" (38mm)



OR



Desk thickness
up to 1.5" (38mm)



Ø 2" (51mm)
minimum

2



Tighten to
60-80 in-lbs.



If the monitor arm or pole does not easily fit into the mount, remove the bushing from the mount and place it on the monitor arm or pole and press firmly back into the mount.

2a



2b



2c



3


6mm
L

4


6mm
L
Tighten to
60-80 in-lbs.
Desk thickness
up to 1.5" (38mm)
N
Ø 3/8"
(9-10mm)
O
P

5



6



7



8



9



10

IMPORTANT!

- Monitor must be on arm
- Arm must be in mount





Press the arm down to approximately parallel with the desk prior to turning the strength adjustment screw.



If the arm **drifts upward,** turn the adjustment screw clockwise.



If the arm **drifts downward,** turn the adjustment screw counter-clockwise.

Depending on the weight of your monitor, **you may have to make 15-20 turns.**

Optional Adjustment



In some instances, an additional counterbalance adjustment may be needed to allow the arm's instant height adjustment function to work properly.

If your arm is not staying in position after performing step 10, tighten the adjustment screw as shown.

11



12



HUMAN ACTIVE TECHNOLOGY™

8428
Installation Instructions

HORIZONTAL POSITIONING

1*



* Monitor arm not included.

2

2x



3

2x



4

2x



800 524 2744 team-hat.com

© 2024 Human Active Technology, LLC P509320 REV C

VERTICAL POSITIONING

1*



* Monitor arm not included.

2



3



4



PARTS LIST

ITEM	DESCRIPTION / PART NO.	QUANTITY
A 	Rotation Prevention Bracket 106271	1
B	10-32 x 1/2" FPhMS 709129	4
C 	M4 x 12mm Pan Head Screw 701153	8
D 	75/100mm VESA® Adapter 109464	2