















VERTICAL WALL TRACK


Installation Instructions




HM-WT002


Parts List


A Wall Track Mount 1x 8328 	F 1/2" Standoff 4x 704920 	K Forearm Cap 1x 111900 	P Wall Track Cable Cap 1x 104985-31 
B Spring-Assisted Monitor Tilter 1x 407747 	G Dog Washer 1x 105189 	L Endcap Bumper 1x 702829 	Q 3/32" Allen Wrench 1x 700146 
C Rotation Prevention Bracket 1x 702949 	H 10-32 x 3/8" FPhMS w/Lock Patch 1x 705198 	M Cable Cap 1x 109344 	R 7/32" Allen Wrench 1x 701127 
D 10-32 x 5/8" Phillips Flat Head Screw 4x 702200 	I Velcro 2x 701174 	N Track Mount Cable Cap 1x 104599 	
E M4 x 18mm Phillips Pan Head Screw 4x 704917 	J Mouse Holder w/Velcro Strips 1x 415267 	O Wall Track End Cap 2x 104596 	





Mounting hardware not included.
Use appropriate hardware to
secure to the mounting surface.















OR













IMPORTANT!

- Monitor must be on arm
- Arm must be in mount



If the arm **drifts upward**,
turn the adjustment screw
clockwise.



If the arm **drifts downward**,
turn the adjustment screw
counter-clockwise.

Depending on the weight of your monitor, **you may have to make 15-20 turns.**

